Launch Director Checklist

NS- 72

Launch date: Nov. 18 2017		
Payload Lineup:	Cml	
	Loka / 360	
	FISH	
		2

Balloon Size(s): 3000g

Callsigns: W3EAX - 8, -12

Pre-Flight Checklist Charge: ✓ Car battery Wi-fi hotspot(s) Walkie-Talkie(s) Check Inventory of: **BLT Bucket** Inflation Bucket Recovery Bucket Launch Kit Main tracking box Launch Equipment Balloons Helium tanks Tarp (Big and Small) Parachute and Ring Command Module kit Broom Trash Bag Square Plywood Bases Scale for Measuring Payloads Recovery **Bow Saw Extension Pole** Scythe ✓ Sling Shot Payloads Car battery

Assume Recovery Talkes: +	Battery box Battery Charger Payloads Soldering Iron & wire Spare LVCs Tyler's Weather Ground Station Tracking/Communications Tracking Laptop(s) Tracking Antennas 900s Ground station Radios Walkie-Talkies Wi-Fi hotspot(s) Power Inverter Power Strip(s) Car magnets
	Launch/Inflation Setup Pre-launch setup meeting (See PAO) Tarp setup (indicate full or half configuration) Place BLT in optimal launch location Indication direction of payload string from balloon Parachute-to-balloon lanyard configured Parachute and ring untangled Command Module in place Harmless payload stickers on each payload Payload string lined up and assembled

Pre-Inflation Checklist
Hook lanyard from parachute around balloon neck before connecting to
inflation tube
Brief 2 tether handlers (See PAO)
Did Dr. Bowden call the tower? (See Dr. Bowden) 1-5
Balloon in BLT ready to go (See BLT Engineer)
Pre-Release Checklist
Cheek payloads are ready
Final communications check
Countdown & Release
Inform payload PoCs to hold payloads above the launch pad
Tether handlers ready
Slowly raise payload string
Measure Total Free Lift = (optional)
Countdown from 10 (Final Countdown Song Optional) Release!
Nelease!
Release Time Mark =

Note: Launching in the roun is not receared and