Flight Director Checklist

NS-<u>60</u>

Laur	ich Location = Clearspring Pork		
	nch Date = Sunday November 1	3:2016	
	Attempt Number = 1		
		w/ duct	reported
Douloador	Cmd	~ 3.9 lbs	
Payloads:		~z. 1 lbs	h 9
,	Aerodynamic Stabilization THEAR SOS	~1.65lbs	1.5
7	Decent clocky	~1.4Ms	1.3
	MARSI	~ 0.2.(b=	•
	FLI		
	MARSIT	~6.53lbs	
	GLIDIR	- 1 lb	
	{Turion?	~1 lb	
	{ Hermes?	-(lb	
Comments:			

Comments:

AEROSS AEAR SOS Decent Valout Tyrion Herus Mars I Must Suppl

Max Alt approx. 86,600 fb Actual: 86,999.76fb

Pre-Flight Planning Checklist Send the launch announcement email Create Zello station UND US-GO Print waivers Preliminary weather check Preliminary ground track check Payloads determined and ordered Vehicles identified and configured for tracking Pre-Flight Systems Checklist BLT Bucket (check Inventory) Recovery Bucket (check Inventory) Recovery Bucket (check Inventory) Balloons (2) Size of balloon 1 1600 a Size of balloon 2 6000 a Batteries (check if charged) Bow Saw(2) Clean Up Bucket (Broom, Dust Pan, Garbage) Extension Pole Functioning Radios and GPS Helium ig ates Mach ete	One Month in Advance: Vehicle Rental (check that outlets work) Helium Ordered HAM Radio Club notified about using UMD's call sign
✓ Send the launch announcement email ✓ Create Zello station UMD US.GO ✓ Print waivers ✓ Preliminary weather check ✓ Preliminary ground track check ✓ Payloads determined and ordered ✓ Vehicles identified and configured for tracking Pre-Flight Systems Checklist ✓ BLT Bucket (check Inventory) ✓ Inflation Bucket (check Inventory) ✓ Recovery Bucket (check Inventory) ✓ Launch Kit (check Inventory) ✓ Bałłoons (2) Size of balloon 1 1600 a Size of balloon 2 1600 a ✓ Batteries (check if charged) ✓ Bow Saw(2) ✓ Clean Up Bucket (Broom, Dust Pan, Garbage) ✓ Extension Pole ✓ Functioning Radios and GPS ✓ Helium ✓ igates ✓ Mach ete	Launch Week
BLT Bucket (check Inventory) Inflation Bucket (check Inventory) Recovery Bucket (check Inventory) Launch Kit (check Inventory) Bałloons (2) Size of balloon 1 1600 a Size of balloon 2 1600 a Batteries (check if charged) Bow Saw(3) Clean Up Bucket (Broom, Dust Pan, Garbage) Extension Pole Functioning Radios and GPS Helium igates Mach ete	 ✓ Send the launch announcement email ✓ Create Zello station UMD US.GO ✓ Print waivers ✓ Preliminary weather check ✓ Preliminary ground track check ✓ Payloads determined and ordered
Parachute and Ring + Assembled Command Module kit Payloads Phone Chargers Power Inverter Scythe Soldering Iron & wire Sling Shot Spare LVCs	BLT Bucket (check Inventory) Inflation Bucket (check Inventory) Recovery Bucket (check Inventory) Launch Kit (check Inventory) Balloons (2) Size of balloon 1 1600 a Size of balloon 2 1600 a Batteries (check if charged) Bow Saw(2) Clean Up Bucket (Broom, Dust Pan, Garbage) Extension Pole Functioning Radios and GPS Helium ig ates Machete Parachute and Ring + Assembled Command Module kit Payloads Phone Chargers Power Inverter Scythe Soldering Iron & wire Sling Shot Spare LVCs

Tie in complete Exempt payloads: Aero Stab, Hermes, Glider Tarp (Big and Small) Tracking Antennas Tree Climbing Gear Van Keys Walkie-Talkies Vs Wi-Fi-hotspot 900s Ground station
FAA Notification Checklist
 File NOTAM (6 hours prior) Call NOTAM desk (866-225-7410 ext 9) to get NOTAM number: NOTAM # Call Washington Center (2 hours prior): 703-771-3470 Call HGR Tower 301-797-2039 at 7am
Radios + Callsigns Checklist
Command Module:
Main tracking van:Second tracking van:
Main tracking van:
Main tracking van:Second tracking van:
Main tracking van:Second tracking van:
Main tracking van: Second tracking van: Specific payloads: ———————————————————————————————————
Main tracking van: Second tracking van: Specific payloads: Others:

- Assign/prepare for jobs (BLT, Comms, Nav, etc.)
- Chase Vehicles will need to leave semi-immediately be ready to leave within 5-10 minutes of launch
- Everyone helps clean up, so we can get out efficiently

Final Checks Waiver Check Weather Check Ground Track Check Zello Check		
Main	Secondary	5 trusque
Prover. Date fulltime	Michael Walker Leven 20 - chuse Luke?	Tyler filline

Launch Day

Parachute to Balloon lanyard configured Parachute and Ring assembled Command Module in place Payload string lined up and assembled Harmless payload stickers on each payload Payload string weighed: Necessary Free Lift = Antennas in place No sharp edges or weak links
Pre-Inflation Checklist Helium Tanks uncovered and regulator hooked up Hook lanyard from parachute around balloon neck before connecting to inflation tube! Instructions and Gloves to BLT anchors Instructions given to tether handlers & tether in place Full payload string laid out and ready to go Balloon in BLT ready to go
Inflation
BLT Instructions: (Always use BLT!!!) Lay out BLT with inside facing up (Velcro side down). Immediately fold together to prevent moisture from getting inside the BLT. When ready for inflation, Place balloon in the center with the neck facing one open end. Fold around the balloon, the Velcro seem should be towards one side so it doesn't end up on the top when fully inflated Designate people to hold BLT down. (At least 4 people)
Start inflating at max flow rate Inflation Complete: Measure Total Free Lift =
Pre-Release Checklist Check payloads are ready Good final communications check

- GLIDR' ground startion ready
ease
Countdown & Rel rned o
/ All Payloads tu n
Raise Stack above pad in full flight configuration
Telemetry and Downlink good
Tether handlers ready
Countdown from 10
Release
Release Time Mark =
Initial Heading of Flight =

Post launch (during chase)

Command Module Checklist

NS-60

Pre-Flight Checklist Cell Tracker Cell Tracker GPS Connection Cell Tracker SD Card Cell tracker cellular connection Power connection Habduino (Top Plate) Habduino GPS Connection 2M RF Connector (Out the back) Power connection Habduino (Bottom Plate) Habduino GPS Connection 2M RF Connector(Out the front) Power connection Link Antenna Connection 1 Antenna Connection 2 Power connection **Systems Check** Top Plate Top LVC Switched on Cell Tracker On Habduino On Receive Text from cell tracker Received Packets from Hab Place desiccants -Bottom Plate **Bottom LVC Switched on** Habduino On LINK On Received Packets from Hab with ground) Place desiccants

Seal Box - if all steps are checked do the following

REMOVE BEFORE FLIGHT